

Clean the hydraulic fluid side of the cooler



Ethylene perchlorate detergent can be used. Pump the detergent through the cooler for 10 minutes.

Do this task when the pump is not operating.

- 1.** Disassemble the cooler to find the degree of contamination.
- 2.** If contamination is moderate, connect the oil side to a closed cleaning system with a pump and a filter. If contamination is very bad, use an oil carbon detergent.
- 3.** Rinse cleaned surfaces for 30 minutes.
- 4.** Use compressed air to remove remaining detergent.
- 5.** Rinse the cooler with operation or equivalent oil.